

"X PHENIX WEEKLY PLANNING



5/2/2013 Don Lynch

This Week

- Run 13 Continues: run support maintenance
- No scheduled access this week: next maintenance day: 5/8
- Ethane Tube Trailer Upgrade Continues:
 Procedure Done, Plumbing fittings Acquired
- mRPC Test Lab (Formerly RPC Factory): Blue Sheets done, UPS needs repair,
 Procedures done and done and done ready for approval signatures
- Continue VTX strip pixel stave re-design
- Continue sPHENIX support
 - HCal prototype design being firmed up
 - EMCal prototype design continuing
- Continue MPC-Ex design
- Future IR evolution modeling



TECHNICAL NUPPORT 20-3

Next Week

- Run 13 Continues: run support, general maintenance
- Next Scheduled Maintenance Day: Wednesday, May 8
- mRPC Test Lab (Formerly RPC Factory) Startup and Walkthru
- Continue VTX strip pixel stave re-design
- Continue sPHENIX support
- Continue MPC-Ex design
- Future IR evolution modeling





Ethane Trailer Project: In progress









mRPC Test Lab Project





VTX Repair Project Progress





Prototypes of updated stave design are in progress expect to be fabricated by end of April









PH^{*}ENIX

2013 VTX/FVTX Repair/Upgrade/Restoration (cont'd)



2013 VTX/FVTX Repair/Upgrade/Restoration (cont'd)





Existing vacuum bellows anti-squirm In MPC S Cavity





Proposed vacuum bellows anti-squirm
In MPC S Cavity to accommodate MPC-Ex

1st Tungsten Plate received: Inspection OK




TECHNICAL

NUPPORT

2013

Window Washer Winch Upgrade



Purchase Order Pinned



with latching hook

Supplied loose

Quotation #: 83944R1


Quotation Date: April 23, 2013 Page: 1 of 5

Attention: Donald Lynch


Company: Brookhaven National Lab

| Phone | : 631-3 | 44-2253 | | |
|--------------|----------------|---|---------------|--------|
| | on the lowing: | information provided to us for an AC hoist to be used for lifting, w | e are pleased | to pro |
| Line | Qty. | Product: | Net Each | Exten |
| 1 | 1 | Columbia HF2100-2A17-L-03 AC Electric Hoist 2.0 HP TEFC UL-listed brakemotor 230/3/60 input power Automatic, load-suspending braking system Permanently lubricated, high-efficiency planetary gear reduction Argent gray enamel paint finish Includes single speed low voltage controls Reversing motor starter in a NEMA 4X fiberglass enclosure UL-listed UL-listed Includes NEMA 4X hand-held pendant control with UP/DOWN momentary contacts and up to 15' lead | \$5,022.00 | \$5,02 |
| <u>Optio</u> | ns: | · | | |
| Line | Qty. | Product: | Net Each | Exten |
| 2 | 1 | AutoAdvance Line Spooler Designed and built for Columbia HF2100-2A17-L-03 Incoming line from front of spooler Fabricated steel frame Sheaves are steel construction, grooved for 3/8" line Ensures proper line spooling regardless of fleet angle Rope tension must be maintained for proper operation | \$3,298.00 | \$3,29 |
| Line | Qty. | Product: | Net Each | Exten |
| 3 | 1 | VLS-6 Vertical Lead Sheave 6,000 lbs load limit Can be bolted down or welded for installation Fabricated steel construction Offset design allows for simple installation at any angle Bronze bushed steel sheave grooved for 3/8" wire rope | \$458.00 | \$45 |
| Line | Qty. | Product: | Net Each | Exten |
| 4 | 1 | Wire Rope • 200' of 3/8" stainless steel wire rope (7x19 construction) | \$684.00 | \$68 |

sPHENIX



201




sPHENIX Proposed Upgrade


Work continues evaluating engineering tradeoffs for EMCal and HCal design, materials, etc.

Prototype HCal and EMCal in progress

Bid packages for Hcal steel and scintillators in progress to be issued by end of the month

Meeting tomorrow with Magnet experts (Friday 4/26) to define SMD participation to develop SC Magnet preliminary design report by July






5/2/2013

14



HCal Prototype Assembly Including 2 rotational DOF's



Expect to place order for HCal prototype parts next week



Major Projects This Summer:

- VTX repairs/upgrades/general maintenance (Mike L.)
- DC East Window Replacement (Kenny J.)
- MPC-Ex Initial (partial) Installation (Jim L.)
- mRPC Tests in mRPC Test Lab (formerly RPC Factory) (Frank T.)
- sPHENIX Prototypes assembly & tests (All)
- MuTr troubleshooting and Repairs (Chris P.)
- Window Washer Winch upgrade (Jim L.)

Other Mechanical (TBD)

Other Electrical Projects

- HVAC Controls Upgrade (Frank T.)
- Complete Window Washer Controls Upgrade (Frank T.)

Other Electronics Projects

- Additional upgrading of ADAM system to MODBUS (Sal P.)
- Electronics research in support of sPHENIX and RATCAP (Sal P.)
- Lecroy HV comminuications upgrade (Sal P.)

Other Gas System Projects (TBD)

- RPC Gas Recirc. Upgrade (John T.)
- Drawing and Config. Control Improvements (SULI Student)

Other Infrastructure Projects (TBD)





| T |
|-------|
| E |
| ECHO! |
| H |
| N |
| + |
| ŧ |
| Ā |
| AL |
| _ |
| S |
| u |
| P |
| NUPP |
| 0 |
| R |
| ORT |
| |
| 201 |
| 0 |
| 1 |
| 0 |

| | 0.444.4.44.40040 |
|--|------------------|
| Prep for 2013 shutdown | 2/11-6/11/2013 |
| Design, Fabricate MPC-Ex | |
| Define tasks and goals | |
| Analysis and design of fixtures, tools and procedures | |
| Fabricate/procure tools and fixtures | |
| Tests, mockups, prototypes | |
| Receive, fabricate, modify, finish installables | |
| Review and approval of parts, tools, fixtures and procedures | |
| Assembly and QA tests | |
| VTX Strippixel redesign | In-progress |
| VTX Strippixel 1st article stave assembly | 5/3/2013 |
| VTX Strippixel 1st article qualification/performance tests | 5/17/2013 |
| VTX strippixel stave production | 5/20-8/30/2013 |
| VTX Strippixel sensor reclamation | 4/1-8/30/2013 |
| VTX Strippixel ladder assembly | 6/1-9/27/2013 |
| Pixel Ladder repairs | in progress |
| End of Run Party | 6/28/2013 |
| Run 12 Ends | 6/11/2013 |
| Shutdown Standard Tasks | 6/11-7/19/2013 |
| Open wall, disassemble wall, Remove MuID Collars, | 0,11,,12,,1010 |
| • Move EC to AH, etc. | |
| Disassemble VTX/FVTX services | 7/1-7/19/2013 |
| July 4th Holiday | 7/4-5/2013 |
| Remove VTX/FVTX and transport to Chemistry Lab | 7/8/2013 |
| Assemble, Test and Install MPC-Ex (North only?) | 7/22-10/1/2013 |



TECHNTO

| | sPHENIX HCal Prototype Assembly/test |
|------|---|
| AL | Labor Day Holiday |
| | Repair upgrade, reassemble VTX/FVTX (pixels and strip-pixels) |
| | Test, survey (at Chemistry and IR) and re-install VTX/FVTX |
| > | Other detector maintenance as required |
| u | Infrastructure maintenance as required |
| P | TBD prototype tasks |
| SUPP | Pre-run commissioning and prep for run 14 |
| 0 | Veterans Day, Lab Holiday |
| R | Prep for EC roll in |
| T | Roll in EC |
| • | Prep IR for run |
| 2 | Thanksgiving Holidays |
| 0 | Pink/Blue/White sheets |
| 1 | Christmas Holiday |
| 3 | New Year's Day Holiday |
| | Start run 14 |

MuTR Troubleshooting, maintenance and repairs

DC East Window Upgrade and Related Repairs

Summer Sunday (8/11) Prep and teardown

Summer Sunday (RHIC)

| 7/22-9/27/2013 |
|------------------|
| 8/7-8/13/2013 |
| 8/11/13 |
| 8/19-9/27/2013 |
| 8/19-10/15/2013 |
| 9/2/2013 |
| 7/11-10/13/2013 |
| 10/16-10/27/2013 |
| As required |
| As required |
| As required |
| 11/1-12/31/2012 |
| 11/11/2013 |
| 11/1-11/9/2013 |
| 11/10-11/12/2013 |
| 11/1-11/30/2013 |
| 11/28-29/2013 |
| 12/14-12/31/2013 |
| 12/24-25/2013 |
| 1/1/2014 |
| 1/2/2014 |
| |



1. Vehicle Accidents:

- a. Any accidents with Government Vehicles on and off site must be called into your Supervisor and BNL Police as soon as it happens.
- b. The Supervisor must call ESSHQ Division as soon as possible.
- c. The same reporting should follow any private vehicle accidents if they are onsite.
- d. This is becoming an issue at BNL, i.e., delays in vehicle accident reporting.
- e. If we don't want DOE to further reduce our vehicle fleet, please always follow these requirements.

2. Ladder Safety

See Website with ~12 minute video: www.stopconstructionfalls.com

3. **LOTO**:

New LOTO Subject Area should be out in a few weeks. Includes table on energy sources provides threshold information to evaluate whether lockout/tagout should be considered or is required.






| Form of Energy | Consider Use of Lockout/Tagout Based on Results of Analysis | Lockout/Tagout is Required* | |
|----------------------------------|---|--|--|
| Electricity AC 60 Hz | >50 V and <5 mA Or < or = 50 V | >50 V and >5 mA | |
| Electricity DC All | >50 V and <=40 mA or < = 100 V | >100 V and >40 mA | |
| Electricity Capacitors All | Other than values specified in right hand column | Stored energy >100 V and >1 J, or >400 V and >0.25 J | |
| Electricity Batteries All | <100V | >100 V | |
| Electricity Sub-RF 1 Hz to 3 kHz | >50 V and <5 mA Or < or = 50 V | >50 V and >5 mA | |
| Electricity RF | All** | N/A | |
| Thermal Energy (Hot) | Liquids less than 120°F (52°C) | Liquids equal to or greater than 120°F (52°C)*** | |
| Thermal Energy (Cold) | Liquids greater than 27°F (-3°C) | Liquids equal to or less than 27°F (-3°C) | |



| Form of Energy | Consider Use of Lockout/Tagout Based on Results of Analysis | Lockout/Tagout is Required* |
|-------------------------|---|------------------------------|
| Mechanical Motion | All | N/A |
| Potential Energy | All | N/A |
| Pneumatic Energy**** | Equal to or less than 150 psi | Greater than 150 psi*** |
| Hydraulic Energy**** | Equal to or less than 150 psi | Greater than 150 psi*** |
| Nonionizing Radiation** | Other electromagnetic radiation | Class 3B or class 4 lasers** |
| Ionizing Radiation | Potential to exceed administrative control level - consult with operating department prior to starting work | N/A |
| Chemical | All | N/A |





FY12: FY11: DART - 30, TRC - 44, First Aid - 45 Recent Injuries

FY13 Injury Listing: https://intranet.bnl.gov/esh/shsd/seg/Occlnj/BNLInjuries.aspx

| 4/18/13 | First Aid | An employee fell on the sidewalk, receiving minor abrasions. |
|---------|------------|---|
| 4/17/13 | DART | An employee was removing a motor from an A/C unit when he injured his arm. He received first aid at the OMC. However, he subsequently was put on restrictions making this recordable and a DART case. |
| 2/5/13 | Recordable | An employee was manually handling boxes of files and injured her shoulder. At the clinic, an examination was conducted and the employee returned to work, with no medical treatment. UPDATE: She later received a steroid shot and a prescription for physical therapy, making this recordable. |
| 2/4/13 | Recordable | An employee developed numbness and tingling in her right arm after using the computer. An ergonomic evaluation was performed. At the OMC, the employee received first aid. After an evaluation, the worker began a regimen of physical therapy. |





| Recent Events | | |
|---------------|--------------------|---|
| 4/26/13 | Non- Reportable | An LPD Officer was dispatched to the West parking lot of building #911 in reference to a government vehicle accident. Driver was backing a government van out of a parking space and backed into a dumpster. Driver states he received no injuries, and further states he didn't see the dumpster while backing up. Damage to the van was contained to the right rear break light area. (Event Link) |
| 4/25/13 | Non- Reportable | A worker was operating a Government Vehicle [E-35361] (a long-bed pick-up truck with a canopy over the bed), and attempting to leave the parking lot outside Building 528. While backing up and turning the vehicle, the rear driver's side bumper/quarter panel/corner of the vehicle scraped against the exterior surface/corner of Bldg. 528. While there were no injuries, some surface damage occurred both to the vehicle and the building. The worker immediately parked the vehicle back in the lot and called for Laboratory Protection Division to report incident. LPD called the ORPS Categorizer after arriving on-scene. (Event Link) |
| 4/22/13 | SC-BNL | Two Lock Out / Tag Out (LOTO) red tags with the same identification number were found in use within a Photon Sciences facility. Photon Sciences personnel are investigating to determine how many tags with duplicate numbers are in service. The red tags are only part of the LOTO process. Systems that are LOTO'd out of service are also locked. The systems found with the duplicate tag numbers have unique locks and it is expected that is true for other systems that may be found to be tagged with duplicate numbered tags. There is no failure to follow the LOTO process and no added risk to personnel from this finding, but management is concerned to find the duplicate numbers as it could be a source of confusion. PS Management has decided to identify this event as an SCBNL, "Management Concern" to alert others at the Laboratory of this finding as these red tags are BNL stock items that are in use across the site. (Event Link) |





TECHNICAL SUPPORT 2013

Where To Find PHENIX Engineering Info



My Pick: 1-2-3

Revolutionary, Veranzano, Oxbow)

Kentucky Derby this Saturday

Watch All Day on NBC Sports Channel

Watch the Race 4:00-7:00 PM on NBC

Horses to Watch:

Goldencents (10-1), Revolutionary (8-1),

Veranzano (9-2), Orb (9-2), OxBow (35-1),

Falling Sky (50-1), Overanalyze (10-1),

Itsmyluckyday (12-1) (best name), Normandy

Invasion (10-1), Java's War (16-1), The rest:

Black Onyx, Charming Kitten, Fear the Kitten, Frac Daddy, Golden Soul, Lines of Battle, Mylute, Palace Malice, Vyjack, Will Take Charge (all 20-1 or more)

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm